

Replacement Sheet




FIG. 7




FIG. 10




FIG. 11




FIG. 18A

Replacement Sheet




FIG. 20B

File Edit Operate Project Windows Help	
Dept Application Font	
Color Location Learn Parameters Learn Mode HSL Shift Information Feature Mode Color Sensitivity Low Sensitivity Low Sensitivity Low Sensitivity Low Sensitivity	
Search Parameters Search Strategy Number Matches Expected Number of Matches Conservative Match Mode Minimum Match Score Shift Invariant Minimum Match Score From 15	
Matching Matches Position x 182.00 y 183.00 Angle 0.00 Scale 1.00 Score 998.69 Bounding Box	
y 176.00	V

FIG. 21




FIG. 22




FIG. 23

This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

BLACK BORDERS

IMAGE CUT OFF AT TOP, BOTTOM OR SIDES

FADED TEXT OR DRAWING

BLURRED OR ILLEGIBLE TEXT OR DRAWING

SKEWED/SLANTED IMAGES

COLOR OR BLACK AND WHITE PHOTOGRAPHS

GRAY SCALE DOCUMENTS

LINES OR MARKS ON ORIGINAL DOCUMENT

REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

IMAGES ARE BEST AVAILABLE COPY.

☐ OTHER:

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.